ZERO-LEAK GOLD[®] PLUG TROUBLESHOOTING

LEAK CHECK PROCEDURE

There may be instances when a leak is detected at a port with a Zero-Leak Gold Plug installed. It is necessary to determine the root cause of that leak in order to correct and prevent the leak. The Troubleshooting Checklist for discovering the leak root cause and establishing Corrective / Preventive Action is designed for those situations.

NOTE BEFORE BEGINNING TROUBLESHOOTING

The Leak Check Procedure may be continued once it has been determined that a ZLGP is in the port. Proceed through each step listed below in sequence until a determination of the root cause and Corrective / Preventive Action of the leak are made.



3. Confirm that the ZLGP was installed to the optimum torque value. A suggested starting point for the final determination of the torque value for individual applications may be found at www.zeroleak.com under Torque Values. The installation torques shown are as a result of the specific testing parameters completed by the Fluid Power Institute located at the Milwaukee School of Engineering. Should a failure occur at the suggested torque value, shut down, clean port and plug, reinstall, and increase torque value by 5%. Repeat the process until a successful torque value is established for the particular application. Results / Findings			
Initials Date			
Is a calibrated torque wrench used to install the ZLGP? Confirm calibration status of the torque wrench. <u>Results / Findings</u>			
InitialsDate			
Are there any nicks or other visible damage to the tapered surfaces of either the ZLGP or the port that could cause a leak path by preventing the metal-to-metal seals to engage? Replace any components that have damaged tapered sealing surfaces.			
Results / Findings			
Initials Date			
Is there any interference with the ZLGP tapered surface seating completely in the port that would prevent the tapers on the ZLGP and in the port from engaging?			
Results / Findings			
Initials Date			

	7.Confirm that the port either SAE J 1926 or not exist. An out of round conditi formed. It may also pro <u>Results / Findings</u>	configuration is 1) concentric (taper to thread) and conforms to the metric port standard ISO 6149 and 2) an out of round port does on in port configuration will prevent a metal-to-metal seal from being ovide a leak path through which the O-ring may be extruded.		
	Initials	Date		
	8. Was the port produce Are all port tool dimens	ed with a one-piece form tool? sions within their tolerances? See #7 above.		
	<u>Results / Findings</u>			
	Initials	Date		
	9. Was the port produce	ed in a multi-step and/or multiple tool process?		
	Results / Findings			
	Initiala	Deta		
П	10. Are the tapers of the	• ZLGP and the port the same for mating components?		
ш	-02 thru -06 must be 7 Results / Findings	12 degrees and -08 and larger 15 degrees.		
	Initials	Date		
	11. Are other SAE J514 or Metric configured plugs experiencing leaks at the same size port?			
	<u>Nesuls / Endings</u>			
	Initials	Date		

	12. Are there other ZLGP of the same size installed in the same system? Are any of those ports leaking?			
	a.	If some ports are not leaking, exchange the plugs in the ports - those ports where leaks are observed with those where leaks are not observed. Wipe away all fluid from all ZLGP and ports prior to making the changes.		
	b.	Pressurize the system and apply the same conditions under which the leaks were initially reported and observe the results. Does the same port leak? Does the previously leak free port leak with the ZLGP from the reported leaking port? If the original leaking port continues to leak and the port that received the ZLGP from the leaking port does not, the root cause of the leak may be focused on the port.		
	Res	sults / Findings		
	Initia	als Date		
	13. O b	oserve the source of the initially reported leak. Is the fluid coming from one area or is it		
	un	iform around the circumference of the port?		
	a.	If the source of the leak is in one location, scribe the location of the leak on the head of the ZLGP and on to the port.		
	b.	Wipe away all fluid from the port and ZLGP and exchange the ZLGP in the leaking port(s) with a ZLGP from a non-leaking port, pressurize the system and observe the results.		
	Res	sults / Findings		
	Initi	als Date		
	14. Co	ontact an EPCO Applications Consultant for additional assistance or clarification if the		
	roo	ot cause of the leak has not been identified after completing all 13 steps of the check		
ш	τ. ease send this sheet, with the Results / Findings sections completed, to FPCO for further			
	assistance.			
	Res	sults / Findings		
	Initi	als Date		